

FIG 2




FIG 1a




FIG 1b

10990034



22-141 50 SHEETS  
22-142 100 SHEETS  
22-144 200 SHEETS




Fig. 1c




Fig. 3a




Fig. 3b




22-141 50 SHEETS  
22-142 100 SHEETS  
22-144 200 SHEETS

15006601

FIG 4

10



00492222 042200

\_\_\_\_\_ 100

A hand-drawn diagram of a stepped profile. The profile consists of three steps of increasing height from left to right. The first step is labeled 102, the second 104, and the third 100. Arrows point from the labels to the corresponding steps.

A hand-drawn cross-section of a stepped profile. The profile consists of a series of horizontal and vertical lines forming a stepped shape. On the right side, there are two dimension lines with arrows pointing to the top and bottom edges of the profile. The top dimension is labeled '106' and the bottom dimension is labeled '100'.

A schematic diagram of a substrate 100. The substrate contains two rectangular openings, 20 and 21. Opening 20 is covered by a conductive layer 56, and opening 21 is covered by a conductive layer 57. Both conductive layers 56 and 57 are connected to a common ground 58, which is represented by a horizontal line at the bottom of the diagram.

109900.34




FIG. 6




FIG 7

10990034